



360 degree check around equipment



AMIRAL Package 4

Struck By Hazard



GENERAL INFORMATION

A struck by hazard refers to an accident in which a worker was hit and injured by an object or equipment. In order to prevent Struck by incident, the following basic safety reminders must be considered to have a safe working location for everyone.

Why Operator need to DO 360 deg. Check in equipment

1. To ensure NO one is standing nearby or behind the equipment.
2. To ensure NO one is resting underneath the equipment
3. To ensure No one taking shade during hot weather
4. Gives the driver or operator the opportunity to plan the backing path before moving the vehicle.
5. To check Vehicle or equipment condition
6. Help drivers / Operator avoid stationary objects like fire hydrants and light poles.

This might the scenario...



This might the scenario...

